

Basic Detail Report



Silos 114-116: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 114: Concrete Stave, 60' x 18', c. 1989, not currently in use. Silo 115: Concrete Stave, 70' x 20', c. 1970, not currently in use. Silo 116: Concrete Stave, 40' x 16', c. 1900, not currently in use. Image looking up the side of two silos. The one on the left is half the height of the other, and it is missing its roof.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)