Basic Detail Report



Silo 117: County Highway 19, Plainfield, NY

Date 2013-14

Medium Digital image Jpeg

Description

Silo 117: Wooden Attached, not currenly in use. Image of

a barn with a dormer in the middle of its roof. Its siding and roofing are all mis-matched.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)