



Silos 118 & 119: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 118: Concrete Stave, 30' x 16', c. 1900, not currently in use. Silo 119: Concrete Stave, 45' x 16', c. 1950, not currently in use. Close up image of a silo and the barn is it next to. There is a structure between them that has caved in. Snow is covering the rooves and ground.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)