

Basic Detail Report



Silos 120 & 121: Perkins Road, Plainfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 120: Concrete Stave, 40' x 16', c. 1974, not currently in use. Silo 121: Concrete Stave, 30' x 14', c. 1951, not currently in use. Image looking through tall weeds and some trees to the top of a silo. Some of the cement block are painted green at the top.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)