

Basic Detail Report



9265.9 cm, 180PPI)

Silos 120 & 121: Perkins Road, Plainfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 120: Concrete Stave, 40' x 16', c. 1974, not currently in use. Silo 121: Concrete Stave, 30' x 14', c. 1951, not currently in use. Image of a leaning silo along side of a barn. The bottom of silo is surrounded by shrubs and weeds. The grass is green and the driveway is muddy. There are parts of the silo dangling from the top.

Dimensions

Digital Resolution: 2736 x 3648 in., 180PPI (6949.5 x