



Silo 124: Whitford Road, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 124: Concrete Stave, 50' x 18', c. 1968, not currently in use. Image of a large red barn and silo in a snow storm. The paint is starting to wear off the barn siding. There are farm supplies scattered around the barn, covered in snow.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)