

# Basic Detail Report

---



## Silos 130-132: Route 8, Brookfield, NY

### Date

2013-14

### Medium

Digital image Jpeg

### Description

Silo 130: Harvestore, 40' x 18, c. 1982, not currently in use. Silo 131: Clay Tile, 30' x 16', not currently in use. Silo 132: Concrete Stave, 60' x 20', c 1950, not currently in

use. Image of the bottom of a clay tile silo. A few of the tiles are caved in and there is snow on the ground.

### Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)