

# Basic Detail Report

---



## Silos 137 & 138: Hollow Road, Brookfield, NY

**Date**

2013-14

**Medium**

Digital image Jpeg

**Description**

Silo 137: Concrete Stave, 60' x 20', c. 1970, not currently

in use. Silo 138: Concrete Stave, 40' x 16' c. 1970, not currently in use. Image of two silos in front of a barn with a metal roof. Between the two silos there is a large door that is open. The silo to the left of the door is much taller than the other. There is a sign across the driveway from the silo.

**Dimensions**

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)