

Basic Detail Report



Silos 141-143: County Highway 18, Edmeston, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 141: Clay Tile, 30' x 16', c. 1950, not currently in use.

Silo 142: Wooden Stave, 40' x 16', c. 1950, not currently in use. Silo 143: Concrete Stave, 50' x 18', c. 1950, not currently in use. Image of a large yellow barn with white sliding doors on the front. There are two silos to the left of the barn and one to the right. The fenced in barn yard in front of the barn is trampled down.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)