Basic Detail Report



Silos 144 & 145: County Highway 18, Edmeston, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 144: Concrete Stave, 50' x 18', not currently in use.

Silo 145: Concrete Stave, $50' \times 16'$, not currently in use. Image of a weather vein on the top of a snow covered silo.

Dimensions

Digital Resolution: 2736×3648 in., 180PPI (6949.5×9265.9 cm, 180PPI)