Basic Detail Report



Silos 147-149: Academy Road, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 147: Concrete Stave, 60' x 18, not currently in use.

Silo 148: Concrete Stave, $60' \times 18'$, not currently in use. Silo 149: Clay Tile, $30' \times 18'$, not currently in use. Image of a large red barn with two silos and a grain bin in front of it and a third silo on the far side of it. The silo on the left in front is half the height of the one on the left and the one behind the barn.

Dimensions

Digital Resolution: 2736×3648 in., 180PPI (6949.5×9265.9 cm, 180PPI)