



Silos 147-149: Academy Road, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 147: Concrete Stave, 60' x 18', not currently in use.
Silo 148: Concrete Stave, 60' x 18', not currently in use.
Silo 149: Clay Tile, 30' x 18', not currently in use. Image of a pick up truck parked in a snowy driveway along side of a red barn. There are two silos and a grain bin in front of the truck. There is snow falling and an inch or so of snow already on the ground.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)