

# Basic Detail Report

---



## Silos 154 & 155: Academy Road, Brookfield, NY

### Date

2013-14

### Medium

Digital image Jpeg

### Description

Silo 154: Concrete Stave, 80' x 14', currently in use Silo 155: Concrete Stave, 50' x 16', c. 1968, currently in use Amish Farm, sold two other silos to the Amish farm with #129 & 130 Image of a small greenhouse in front of two silos and three barns. The barn on the left has is large barn doors slid open. The barn in the barn is red and white and the barn to the right is totally open on one side. Between them all there is a smaller shed. The silo closer to the camera is half the height of the other. They are all

covered in snow that is still falling.

### Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)