

Basic Detail Report



Silo 159: Beaver Creek Road, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 159: Concrete Stave, 50' x 16', built c. 1970, current use unknown. Image taken from across a road of a red barn with a silo behind it. There are three cupolas on the roof of the barn and a hay elevator in the hay loft window. The ground around it is grown up with weeds.

Dimensions

Digital Resolution: 2736 x 3648 in., 180PPI (6949.5 x 9265.9 cm, 180PPI)