

Basic Detail Report



English Barn, Herkimer County, NY

Date

c.1908

Medium

photographic print on heavy cardstock

Description

Exterior view of a an English barn with double hinged doors on the long side of the barn. These types of doors usually opened to a central threshing floor and a similar set of doors would be opposite these on the other side of the barn. A small closed-over window or a patched in area in the clapboards is to the right of the doors. A wooden split-rail fence is on the right side of the barn. Behind this barn, in partial view is a barn of newer construction. This barn has a dutch door on the right side, probably opening to an animal pen or stable. A small diamond window is to the left of this opening and another window is above it in the eaves. The barns were located in Herkimer County, New York.

Dimensions

Overall: 3 1/2 x 5 3/8 in. (8.89 x 13.65 cm)